

# Contents

Troubleshooting Single-Phase Motors . . . . .	xvii
Troubleshooting Three-Phase Motors . . . . .	xix
Troubleshooting the DC Machine . . . . .	xxi
Introduction . . . . .	xxiii
<b>CHAPTER 1 The DC Machine . . . . .</b>	<b>1</b>
Basic Electricity as It Applies to Motors . . . . .	1
Volts . . . . .	2
Resistance . . . . .	2
Amperes . . . . .	2
Additional Information on Copper Wire . . . . .	3
Ohm's Law . . . . .	5
Watt . . . . .	5
Magnets and the Magnetic Circuits . . . . .	6
The Bar Magnet . . . . .	6
The Electromagnet . . . . .	6
The Magnetic Pole . . . . .	6
Ampere Turns . . . . .	9
The Magnetic Circuit . . . . .	9
Magnetic Saturation . . . . .	11
Magnetic Balance . . . . .	12
Neutral Position in the Stator . . . . .	13
Circuits of the DC Machine . . . . .	13
Rules for Generating Direct Current . . . . .	14
The Shunt Generator . . . . .	15
The Armature and Interpoles . . . . .	15
The Shunt Field . . . . .	16

## vi Contents

Operation of the Self-Excited Shunt Generator . . . . .	17
Shunt Generator Control . . . . .	18
The Series Generator . . . . .	19
Operation of the Self-Excited Series Generator . . . . .	19
The Compound Generator . . . . .	20
The Armature and Interpoles . . . . .	20
The Series Field . . . . .	21
The Shunt Field . . . . .	21
Operation of the Self-Excited Compound Generator . . . . .	21
Compound Generator Control . . . . .	22
The Cumulative Compound Connection (Generator) . . . . .	23
The Differential Compound Connection (Generator) . . . . .	23
Series Field Connections for a Motor and a Generator . . . . .	24
Special-Purpose Machine Connections . . . . .	25
The DC Arc Welder . . . . .	25
Operation of the DC Welder Generator . . . . .	27
Operation of the Welder's Reactor . . . . .	27
Interpoles . . . . .	28
Operation of Interpoles . . . . .	28
The Compensating Winding . . . . .	30
Operation of a DC Motor . . . . .	31
One Armature Conductor in a Generator as It Passes Two Poles . . . . .	31
One Armature Conductor in a Motor as It Passes Two Poles . . . . .	33
Counter-voltage . . . . .	34
Counter-voltage Compared to Charging a Battery . . . . .	34
Counter-voltage in a Motor Armature . . . . .	35
Base Speed . . . . .	36
Below Base Speed . . . . .	36
Above Base Speed . . . . .	36
Torque of the DC Motor . . . . .	37
The Shunt Motor . . . . .	37
The Armature and Interpoles . . . . .	37
The Shunt Field . . . . .	37
Operation of the Shunt DC Motor . . . . .	38
The Permanent Magnet DC Motor . . . . .	39
Operation of the Permanent Magnet Motor . . . . .	39
Restoring Magnetism . . . . .	39
The Series Motor . . . . .	40
Operation of the Series Motor . . . . .	41

The Compound DC Motor . . . . .	42
The Armature and Interpoles . . . . .	42
The Shunt Field . . . . .	42
The Series Field . . . . .	43
Operation of the Compound Motor Connected Cumulative Compound . . . . .	43
The Stabilized Shunt Motor . . . . .	43
Speed Control for a Compound DC Motor . . . . .	44
Armature Control for Starting and for Below Base Speed . . . . .	44
Shunt Field Control for Starting and for Above Base Speed . . . . .	44
The Differential Connection (Motor) . . . . .	45
Armature Components . . . . .	46
Commutator . . . . .	47
Commutator Film . . . . .	48
Armature Windings . . . . .	49
Equalizer Shunts . . . . .	50
Laminated Iron . . . . .	50
Chapter 1 Review . . . . .	51

**CHAPTER 2 Troubleshooting and Testing the DC Machine . . . . . 57**

Armature Problems . . . . .	57
Burned Commutator Bars . . . . .	57
Dirty Commutator . . . . .	57
Dead Spots from an Open Armature Coil . . . . .	58
Open Equalizer . . . . .	58
Stalled Motor . . . . .	58
Control and Load Problems . . . . .	59
Brushes . . . . .	59
Brush Problems . . . . .	59
Conduction Zone . . . . .	60
Spiral Groove . . . . .	61
Multiple Brushes . . . . .	62
Brush Box and Commutator Spacing . . . . .	62
Distance Between Brushes . . . . .	62
Brush Holder Alignment . . . . .	63
Spring Tension . . . . .	63
Brush Shunts . . . . .	65
Side Wear . . . . .	65
Uneven Commutator Segments . . . . .	65

Brush Dusting . . . . .	65
Low Load Current . . . . .	65
Silicone Vapor and Adverse Ambient Conditions . . . . .	66
Seating Brushes . . . . .	67
Neutral Location in the Stator and Armature . . . . .	68
Setting Neutral in a Motor . . . . .	68
Black Band Adjustment . . . . .	69
Setting Neutral in a Generator . . . . .	69
Restoring Residual Magnetism After Setting Neutral . . . . .	69
Overheated Motor . . . . .	70
Field Testing the DC Machine . . . . .	70
Field Testing the Armature . . . . .	70
Field Testing for Grounds in the Armature Circuit with an Ohmmeter . . . . .	71
Field Testing the Shunt Field . . . . .	71
Field Testing the Series Field . . . . .	75
Locating Problems in the DC Machine . . . . .	78
Locating Problems in the Armature . . . . .	79
Locating a Grounded Interpole with AC and a Clamp-on Ammeter . . . . .	80
Locating a Shorted Interpole Using the AC Voltage Drop Test . . . . .	82
Locating a Shorted Interpole Using the Smoke Test . . . . .	83
Locating Problems in the Shunt Field . . . . .	83
The Comparison Test . . . . .	83
Needle Probes . . . . .	83
Variations in the Shunt Field Circuitry . . . . .	84
Drawing Simple Schematics of a Shunt Field . . . . .	84
Drawing a Diagram of a Two-Circuit Shunt Field . . . . .	84
Drawing a Diagram of a Two-Circuit, Two-Coils-per-Pole Shunt Field . . . . .	85
Ground to the Frame Symptom . . . . .	87
Shorted Turns in the Shunt Field Symptoms . . . . .	89
Shunt Field with an Open Circuit . . . . .	91
Shunt Field Shorted to the Series Field Symptoms . . . . .	93
Locating Problems in the Series Field . . . . .	94
Ground to Frame Symptoms . . . . .	95
Shorted Turns in the Series Field Symptoms . . . . .	96
Locating an Open Circuit in Series Field . . . . .	98
Identifying Leads of a Compound DC Motor with an Ohmmeter . . . . .	99
Chapter 2 Review . . . . .	100

<b>CHAPTER 3 AC Electric Motor Theory . . . . .</b>	<b>105</b>
AC Terminology . . . . .	105
Generating Alternating Current . . . . .	105
Cycles and Hertz. . . . .	107
Electrical Degrees and Time. . . . .	108
Electrical Degrees and Mechanical Degrees. . . . .	111
Degrees and Location . . . . .	111
Two-Phase Power. . . . .	111
Two-Phase Rotating Magnetic Field . . . . .	113
Revolutions per Minute, Poles, and Hertz . . . . .	114
The Single-Phase Alternator . . . . .	115
Current, Ampere, Power, and Reactive Terms . . . . .	116
Inductive Reactance . . . . .	116
Impedance . . . . .	118
Inductive Reactance and Counter-voltage . . . . .	118
Power Factor . . . . .	118
Unity Power Factor . . . . .	118
Magnetizing Amperes and Lagging Power Factor. . . . .	119
Power Factor in Motors . . . . .	121
Low Power Factor Concerns . . . . .	121
Inductive Reactance and Hertz Change . . . . .	122
Formula for 50-Hz to 60-Hz Power Change . . . . .	122
Impedance in a Three-Phase Winding . . . . .	122
Capacitance and Capacitive Reactance. . . . .	123
Capacitor Function . . . . .	123
Capacitor Value . . . . .	124
Capacitors for Single-Phase Motors. . . . .	125
Oil-Filled Capacitor . . . . .	125
Oil-Filled Capacitor in Single-Phase Motors . . . . .	125
Oil-Filled Capacitor Components . . . . .	126
Oil-Filled Capacitor Connection in a Two-Value Capacitor Single-Phase Motor . . . . .	126
Mounting the Oil-Filled Capacitor . . . . .	128
Electrolytic Capacitors . . . . .	128
Electrolytic Capacitor Function in the Capacitor-Start Motor . . . . .	128
Electrolytic Capacitor Components . . . . .	131
Electrolytic Capacitor and Start-Winding Connections . . . . .	131
Parallel Electrolytic Capacitor Connection. . . . .	131
Series Electrolytic Capacitor Connection . . . . .	132
Testing the Electrolytic Capacitor. . . . .	133

## x Contents

Capacitor Test Formula . . . . .	134
Determining the Right Size Capacitor . . . . .	135
Operation of the Single-Phase Capacitor-Start Motor . . . . .	137
Transformer Theory . . . . .	138
Transformer Components . . . . .	138
Transformer Function . . . . .	139
Transformer Rating . . . . .	139
Solder Gun Transformer . . . . .	140
The Squirrel Cage Rotor . . . . .	141
Current Flow in Stator Coils . . . . .	142
Function of the Squirrel Cage Rotor . . . . .	144
Rotor Hertz and Amperes . . . . .	145
Slip, Hertz, and Motor Speed . . . . .	145
Synchronous Speed and Zero Torque . . . . .	146
Rotor Bar Stress . . . . .	147
Broken Rotor Bars . . . . .	148
Cracked End Rings . . . . .	148
Misaligned Rotor Iron . . . . .	149
Chapter 3 Review . . . . .	149

## **CHAPTER 4 The Single-Phase Motor. . . . . 155**

Shaded-Pole Motor . . . . .	155
Multispeed Shaded-Pole Motor . . . . .	156
Troubleshooting the Shaded-Pole Motor . . . . .	156
Split-Phase Motor . . . . .	157
Components of the Split-Phase Motor . . . . .	157
Operation of the Split-Phase Motor . . . . .	158
Troubleshooting the Split-Phase Motor . . . . .	158
Capacitor Motors . . . . .	158
The Capacitor-Run Motor . . . . .	159
The Capacitor-Start Motor . . . . .	161
Two-Value Capacitor Motor (Capacitor-Start, Capacitor-Run Motor) . . . . .	172
Capacitor-Start Motor Connections . . . . .	178
Thermal Protective Devices . . . . .	180
Components of the Bimetal Thermal Protective Devices (for Single-Phase Motors). . . . .	181
Connections and Operation of the Thermal Protective Device . . . . .	182
Limitations of Thermal Protective Devices . . . . .	185

Alternative Start-Winding Switches . . . . .	186
Potential Relay Start Switch . . . . .	186
Electronic Start Switch . . . . .	190
Time-Delay Electronic Start Switch . . . . .	192
Heat-Activated Start Switch. . . . .	192
Current Relay Start Switch . . . . .	193
Chapter 4 Review . . . . .	195

**CHAPTER 5 The Three-Phase Induction Motor. . . . . 201**

Components of the Three-Phase Motor . . . . .	201
Rotor and Fan . . . . .	203
Stator Core. . . . .	203
Shell and Frame . . . . .	204
End Brackets . . . . .	204
Bearings. . . . .	205
Operation of the Three-Phase Motor . . . . .	205
The Rotating Magnetic Field in a Three-Phase Motor . . . . .	206
Single-Phase Condition . . . . .	209
Amperes and Rotor Bar Design . . . . .	210
Phase Angle. . . . .	211
Small Rotor Bars . . . . .	211
Large Rotor Bars . . . . .	212
Code Letter . . . . .	213
Torque and Speed . . . . .	213
Design Letter. . . . .	214
Introduction to Three-Phase Motor Types . . . . .	217
The Nine-Lead Induction Motor . . . . .	217
Nine-Lead Wye Connection . . . . .	219
Nine-Lead Multiple-Wye Connection with T10 . . . . .	220
Thermal Protector for the Nine-Lead	
Wye-Connected Motor . . . . .	222
Nine-Lead Delta Connection. . . . .	223
Multiple-Delta Connection . . . . .	224
Twelve-Lead Connection. . . . .	224
Multispeed Motors . . . . .	227
Single-Winding Two-Speed Motors . . . . .	227
Constant-Horsepower Motor. . . . .	228
Constant-Torque Motor . . . . .	229
Variable-Torque Motor. . . . .	229

## xii Contents

Multispeed Multiwinding Motor . . . . .	230
Two-Speed Two-Winding Motor . . . . .	231
Multimode Nine-Lead Three-Phase Motors . . . . .	231
Comparing Multimode Motors to Standard Motors . . . . .	232
Triple-Mode, Nine-Lead Three-Phase Motor . . . . .	233
Identifying the Triple-Mode, Nine-Lead Three-Phase Motor . . . . .	234
Quadruple-Mode, Nine-Lead Three-Phase Motor . . . . .	235
Identifying the Quadruple-Mode, Nine-Lead Three-Phase Motor . . . . .	237
Synchronous Motor . . . . .	237
Components of the Synchronous Motor . . . . .	239
Operation of the Synchronous Motor . . . . .	240
The Synchronous Motor Control . . . . .	241
Power Factor Correction with a Synchronous Motor . . . . .	243
The Brushless Synchronous Motor . . . . .	244
Three-Phase Alternator . . . . .	244
Wound Rotor Motor . . . . .	244
Components of the Wound Rotor Motor . . . . .	245
Operation of the Wound Rotor Motor . . . . .	245
Liquid Used for Speed Control . . . . .	248
Reversing the Wound Rotor Motor . . . . .	248
Wound Rotor Motor Used as a Variable-Voltage Transformer . . . . .	249
Wound Rotor Motor Used as a Hertz Changer . . . . .	249
The Brushless DC Motor . . . . .	249
Components of Brushless DC Motors . . . . .	250
Operation of the Brushless DC Motor . . . . .	251
Three-Phase Servo Motors . . . . .	251
Identifying the Three-Phase Induction Motor . . . . .	252
Nine-Lead Dual-Voltage Motors . . . . .	252
Three-Lead Motors . . . . .	253
Six-Lead Motors . . . . .	253
Twelve-Lead Single-Speed Motors . . . . .	261
Dual-Voltage Multispeed Motors . . . . .	263
European Connections . . . . .	263
Chapter 5 Review . . . . .	269
<b>CHAPTER 6 Troubleshooting Three-Phase Motors . . . . .</b>	<b>275</b>
The Dual-Voltage Nine-Lead Motor's Internal Connections . . . . .	275
Understanding the Nine-Lead Wye Connection . . . . .	275

Understanding the Nine-Lead Delta Connection . . . . .	278
Smaller Wire Size with Delta and Multicircuit Winding. . . . .	281
Identifying Unmarked Leads in a Nine-Lead Three-Phase Motor . . . . .	285
Identifying Unmarked Leads in a Wye Connection . . . . .	285
Identifying Unmarked Leads in a Delta Connection . . . . .	288
Theory of Unmarked Lead Test . . . . .	292
Typical Winding Problems . . . . .	293
Shorted Turns . . . . .	293
Ground . . . . .	294
Phase-to-Phase Short. . . . .	295
Open Winding . . . . .	298
Burned Windings from Operating on Single Phase . . . . .	298
Submerged Motor . . . . .	300
Assorted Rotor Problems. . . . .	301
When Motors Overheat. . . . .	304
Line-Caused Overheating . . . . .	304
Operator-Caused Overheating . . . . .	309
Control-Caused Overheating. . . . .	311
Motor Fault Overheating. . . . .	312
Location-Caused Overheating. . . . .	316
Maintenance-Caused Overheating . . . . .	316
Chapter 6 Review . . . . .	317

**CHAPTER 7 Troubleshooting Less Common Motors . . . . . 321**

Troubleshooting Logic Using Voltage Rules . . . . .	321
Troubleshooting Less Common Motors . . . . .	322
Troubleshooting Identified Motors . . . . .	322
Troubleshooting the Synchronous Motor . . . . .	323
The DC Exciter Field and Discharge Resistor. . . . .	324
The Amortisseur Winding. . . . .	325
Stator Winding. . . . .	326
Troubleshooting the Two-Speed One-Winding Motor. . . . .	327
Troubleshooting Multispeed Multiwinding Motors. . . . .	329
Circulating Current in Multiwinding Multispeed Motors. . . . .	330
Rotor Problems in the Multispeed Motor . . . . .	332
Testing Motors in Place. . . . .	333
Test Instruments for Testing in Place . . . . .	333
Core and Rotor Damage . . . . .	333
Troubleshooting the Nine-Lead Motor (Wye or Delta) in Place . . . . .	334

## xiv Contents

Visual Check of the Nine-Lead Motor (Wye or Delta) . . . . .	334
Testing from Control (Wye or Delta) . . . . .	336
Starting the Motor After the Comparison Test from Control . . . . .	339
Line/Lead Interchange Test for Uneven Amperes. . . . .	339
Recording Motor Faults. . . . .	339
Locating Motor Faults . . . . .	340
Test Equipment for Locating Motor Faults . . . . .	340
Locating Shorted Turns in a Wye-Connected Nine-Lead Motor . . . . .	341
Locating Voltage Spike Damage in a Wye-Connected Nine-Lead Motor . . . . .	342
Locating Shorted Turns in a Delta-Connected Nine-Lead Motor . . . . .	344
Megohmmeter Test for Ground . . . . .	346
Bearing Maintenance . . . . .	346
Motor Storage Concerns . . . . .	347
Bearing Failure Causes . . . . .	348
Lubrication Schedule and Bearing Life. . . . .	350
Grease Types . . . . .	351
Changing Grease Types. . . . .	351
Lubrication Procedure . . . . .	352
Alternate Lubrication Methods. . . . .	353
Gearbox Lubrication . . . . .	353
Shielded Bearings . . . . .	354
Sealed Bearings . . . . .	354
Labyrinth Seal . . . . .	354
Bearing Removal . . . . .	356
Bearing Installation. . . . .	358
Identifying Bearing Breakdown Causes . . . . .	359
Specialized Bearing Tools . . . . .	361
Sleeve Bearings . . . . .	363
Chapter 7 Review . . . . .	363

## **CHAPTER 8 Test Instruments and Services . . . . . 367**

Instruments for Initial Testing . . . . .	367
Voltmeter. . . . .	368
Clamp-on Ammeter . . . . .	369
Ohmmeter. . . . .	371
Microhmmeter . . . . .	372
Tachometer . . . . .	373
Megohmmeter. . . . .	374

Infrared Gun . . . . .	376
Stethoscope . . . . .	377
Instruments for In-depth Testing and Scheduled Maintenance . . . . .	377
Surge Tester . . . . .	378
Rotor Test . . . . .	380
Polarization Index Test with a Megohmmeter . . . . .	381
Step Voltage Test . . . . .	383
High-Potential Test . . . . .	385
Power Quality Test Instruments . . . . .	386
Vibration Sensors . . . . .	388
Laser Alignment . . . . .	389
Particle Analysis . . . . .	390
Chapter 8 Review . . . . .	391
<b>Index . . . . .</b>	<b>393</b>



# Troubleshooting Single-Phase Motors

Capacitor Start Connections	
Two-value Capacitor Start . . . . .	127
Electrolytic Capacitor Rules . . . . .	132, 133, 173
Capacitor Test Formula . . . . .	134–137
Connections . . . . .	174–178
Capacitor/Start-Winding Connections . . . . .	179, 180
Rotor Problems . . . . .	147–149
Troubleshooting the Capacitor Start Motor. . . . .	162
Start Switch Assembly. . . . .	162, 163
Alternative Start Winding Switches . . . . .	186–195
Electrolytic Capacitor . . . . .	164, 165
Start Winding. . . . .	165–168
Run Winding . . . . .	168–171, 183–185
Bearings. . . . .	171, 172



# Troubleshooting Three-Phase Motors

Bearing Maintenance . . . . .	346, 347
Storage Concerns . . . . .	347-348
Failure Causes . . . . .	348-350
Lubrication Schedule . . . . .	350
Grease Types . . . . .	351, 352
Changing Grease Types . . . . .	351
Lubrication Procedure . . . . .	352
Alternate Lubrication Methods . . . . .	353
Gearbox Lubrication . . . . .	353
Particle Analysis . . . . .	353
Shielded and Sealed Ball Bearings . . . . .	354
Removal . . . . .	356, 357
Installation . . . . .	356
Breakdown Causes . . . . .	359-361
Bearing Current . . . . .	359-361
Identifying Unmarked Leads . . . . .	285
Nine-Lead Wye . . . . .	285-288
Nine-Lead Delta . . . . .	288-292
Nine-Lead Wye Circuits . . . . .	276-278
Nine-Lead Delta Circuits . . . . .	281-284
Overheating	
Line Caused . . . . .	304-309
Over Voltage . . . . .	304, 305
Low Voltage . . . . .	305, 306
Unbalanced Voltage . . . . .	306-308
Poor Connections . . . . .	308-309

## xx Troubleshooting Three-Phase Motors

Control Caused . . . . .	311, 312
Motor Fault . . . . .	312–315
Location. . . . .	316
Belt or Pulley Problems . . . . .	316
Rotor Problems	
Open Bars . . . . .	302
Open End Rings . . . . .	302
Misaligned. . . . .	303
Dragging on Stator. . . . .	303
Loose on Shaft. . . . .	303, 304
Testing Motors in Place	
Core Damage. . . . .	333–334
Nine-Lead Motor . . . . .	334–336
From the Control. . . . .	336–338
Line/Lead Interchange. . . . .	339
Troubleshooting Logic Using Voltage Rules . . . . .	312, 313
Uncommon Motors	
Synchronous Motor. . . . .	323–377
Two-Speed One Winding. . . . .	327–329
Multi-speed, Multi-winding. . . . .	329–331
Rotor Problems . . . . .	332
Winding Problems	
Shorted Turns. . . . .	293, 294
Ground. . . . .	294, 295
Phase to Phase Short . . . . .	295–297
Open Winding . . . . .	298
Single Phase Burn . . . . .	298–300
Wet Winding. . . . .	300, 301

# Troubleshooting the DC Machine

Armature Problems . . . . .	57–69
Commutator Film . . . . .	48
Burned Bars . . . . .	57
Dead Spots . . . . .	58
Open Equalizer . . . . .	58
Control, Load Caused . . . . .	59
Brush Problems . . . . .	59–67
Conduction Zone . . . . .	60, 61
Spiral Groove . . . . .	61
Multiple Brushes . . . . .	62
Spacing . . . . .	62
Alignment . . . . .	63
Spring Tension . . . . .	63–64
Brush Shunts . . . . .	65
Side Wear . . . . .	65
Uneven Commutator Segments . . . . .	65
Brush Dusting . . . . .	65
Low Load Current . . . . .	65–66
Silicone Vapor . . . . .	66
Seating Brushes . . . . .	67
Base Speed . . . . .	36, 44
Below Base Speed . . . . .	36, 44
Above Base Speed . . . . .	36, 44
Speed Control (Figure 1.46) . . . . .	44, 45
Connections NEMA Standard	
Shunt Generator (Figure 1.17) . . . . .	15

## xxii Troubleshooting the DC Machine

Shunt Motor (Figure 1.40) . . . . .	38
Compound Generator (Figure 1.25) . . . . .	20
Compound Motor (Figure 1.29) . . . . .	34
Series Motor (Figure 1.43) . . . . .	41
Field Testing . . . . .	70–78
Armature . . . . .	70
Grounds . . . . .	71
Shunt Field . . . . .	71
Ground . . . . .	72
Short . . . . .	72, 73
Open . . . . .	73, 74
Shorted to Series Field . . . . .	75
Series Field . . . . .	75–78
Ground . . . . .	76
Shorted Turns . . . . .	76, 77
Open . . . . .	77, 78
Interpoles . . . . .	28
Polarity and Direction of Rotation . . . . .	28
Left Hand Rule (Figure 1.1) . . . . .	3
Neutral Setting . . . . .	68, 69
In Motor . . . . .	68, 69
In Generator . . . . .	69
Black Band . . . . .	69
Re-magnetizing . . . . .	69
Permanent Magnet DC Motor . . . . .	39
Restore Magnetism . . . . .	39–40
Stabilized Shut Motor . . . . .	43
Differential Connection (Figure 1.47) . . . . .	45, 46
Welder . . . . .	25
Components . . . . .	25–28
Operation . . . . .	28
Welders Reactor . . . . .	28